

CARECLEAN ACC

For manual and "in service" cleaning of Diesel Engine charge air coolers.

- * Effective removal of all contaminants.
- * Anti corrosive properties.
- * No impact on cylinder oil films.
- * Completely combustible in the cylinder.
- * Dosing systems available.

Application

Immersion bath

Dependant on design, the cooler is flooded with Careclean ACC or immersed in a tank full of product. The product should be heated to approx. 50°C and agitation provided with an air line. After 2 hours, drain off and flush well with water, followed by drying with an air line.

Circulation method

Some designs of cooler can be circulated "in situ". In this case a pump tank and pipe system is fitted permanently or connections are provided for connecting a temporary circuit. The system should be filled with Careclean ACC and circulation carried out for 2 - 4 hours at a temperature of upto 50°C.

After cleaning the cooler should be thoroughly flushed with fresh water and dried with an air line.

Note: Both cleaning methods benefit from heat of up to 50°C and cleaning times can be reduced or extended dependant on temperature and degree of fouling.

Direct injection

Careclean ACC has the approval of the majority of major manufacturers for use either in their own design of "in service" cleaning system or other recognised systems provided by suppliers.

Injection systems

Marine Care offer a range of newly developed easy to operate manual systems.

Directions for use

Regardless of the type of "in service" system used, Careclean ACC should be dosed at the ratio of 2 parts water added to 1 part product (in that order) and well mixed for immediate use.

If the emulsion is left standing for up to 5 minutes its composition will change and effectiveness

reduced. It is most important that 5 - 10 minutes after dosing the solution, injection with fresh water only is repeated using double the total volume of the first solution to flush off the chemical residual which contains the "solved" contamination. Failure to do this will result in a "sticky cooler" which will foul very quickly.

Turbo blowers

The water washing of the air side of turbo blowers has been accepted for many years. Most manufacturers provide nozzles and dosing pots to inject water into the volute casing after the inlet filters. These systems can be utilised with a solution of Careclean ACC at the same ratio of 2 parts water mixed into 1 part product and dosed via the water wash system.

Note: When cleaning turbo blowers "in service" follow the equipment manufacturers instructions regarding engine load and/or blower revolutions during the procedure.

As with normal water washing, do not attempt to clean a badly fouled blower as resultant removal of deposits could cause imbalance of the rotor. The principle to follow is prevention not cure.

Injection systems

Marine Care can give advise on modifications to existing equipment or retrofit packages. For further details refer to the equipment information sheet.

Properties

Light yellow coloured neutral fluids, which emulsify with water and are safe in contact with all metals.

Specific Gravity (20°C)	: 0.915
Flash point PM CC	: 87 °C

For detailed information on safety and health, please refer to Material Safety Data Sheet and / or Product label.

The details of our products are given completely free of undertaking. Since their application lies outside our control we cannot accept any liability for the results.